


TEST CIRCUIT TO CHECK WESTACH 720-12R HALL EFFECT SENDER



MULTIMETER MEASURED VOLTAGE SHOULD SWING FROM 0V TO $V+$
WHEN ROTOR SHAFT IS TURNED BY HAND.

0V WHEN A MAGNET IS IN FRONT OF THE SENDER.

$V+$ WHEN A MAGNET IS CLEAR OF THE SENDER.

CHECK ON ALL FOUR MAGNETS ON THE MAGNET RING.

ALTERNATIVELY IF BENCH TESTING A SENDER,
YOU CAN USE THE SOUTH POLE OF A SEPERATE BAR OR ROD MAGNET